
**FIG. 3****FIG. 4**

nikebk|nikebk_1069038557|39669|0|Alliente_MFNVNA01a_COL_S08_FIL_0_1|0|weekly_full|0|3|Nov 16 22:09:17 2003|Dec 17 22:09:17 2003|2109|6942943|129472|0|000ZYV 00192T|2 3|10.41.3.100|CATI

FIG. 5




FIG. 6

CODE	MESSAGE EXPLANATION
0	THE REQUESTED OPERATION WAS SUCCESSFULLY COMPLETED THERE WERE NO PROBLEMS DETECTED WITH THE REQUESTED OPERATION.
1	THE REQUESTED OPERATION WAS PARTIALLY SUCCESSFUL A PROBLEM THAT MAY REQUIRE CORRECTIVE ACTION WAS DETECTED DURING THE REQUESTED OPERATION.
2	NONE OF THE REQUESTED FILES WERE BACKED UP A BACKUP OR ARCHIVE COULD NOT BACK UP ANY OF THE FILES IN THE FILE LIST.
3	VALID ARCHIVE IMAGE PRODUCED, BUT NO FILES DELETED DUE TO NON-FATAL PROBLEMS THE BACKUP PORTION OF THE ARCHIVE COMMAND REPORTED PROBLEMS SO THE FILES WERE NOT DELETED.
4	ARCHIVE FILE REMOVAL FAILED THE BACKUP PORTION OF THE ARCHIVE COMPLETED WAS SUCCESSFUL BUT THE DELETE FAILED.
5	THE RESTORE FAILED TO RECOVER THE REQUESTED FILES THERE WERE ERRORS THAT CAUSED THE RESTORE TO FAIL.
6	THE BACK UP FAILED TO BACK UP THE REQUESTED FILES ERRORS CAUSED THE USER BACKUP TO FAIL.
0000	NO ADDITIONAL SENSE INFORMATION
0401	LOGICAL UNIT IN PROCESS OF BECOMING READY
0402	LOGICAL UNIT NOT READY, INITIALIZING COMMAND REQUIRED
0404	LOGICAL UNIT NOT READY, FORMAT IN PROGRESS
0481	FIRMWARE VERSIONS INCOMPATIBLE
0C00	UNRECOVERABLE WRITE ERROR
0C01	WRITE ERROR RECOVERED WITH AUTO REALLOCATION
0C80	UNRECOVERED WRITE ERROR DUE TO POSSIBLE BATTERY DISCHARGE AND ALTERNATE CONTROLLER FAILURE
0C81	DEFERRED UNRECOVERABLE ERROR DUE TO MEMORY FAILURE
1100	UNRECOVERED READ ERROR
118A	MISCORRECTED DATA ERROR - DUE TO FAILED DRIVE READ
1802	RECOVERED DATA - DATA AUTO REALLOCATED
1A00	PARAMETER LIST LENGTH ERROR
2000	INVALID COMMAND OPERATION CODE
2100	LOGICAL BLOCK ADDRESS OUT OF RANGE
2400	INVALID FIELD IN CDB
2500	LOGICAL UNIT NOT SUPPORTED
2600	INVALID FIELD IN PARAMETER LIST
2800	NOT READY TO READY TRANSITION
2900	POWER ON, RESET, OR BUS DEVICE RESET OCCURRED
2904	DEVICE INTERNAL RESET
2981	DEFAULT CONFIGURATION HAS BEEN CREATED
2982	CONTROLLER FIRMWARE SYNCHRONIZED
2A01	MODE PARAMETERS CHANGED
2A02	LOG PARAMETERS CHANGED
2F00	COMMANDS CLEARED BY ANOTHER INITIATOR
3101	FORMAT COMMAND FAILED
3200	OUT OF ALTERNATES
3F01	DRIVE MICROCODE CHANGED
3F80	DRIVE FAILED DUE TO WRITE FAILURE

FIG. 7




FIG. 8




FIG. 9